

SECRET

Declassification Review by NGA/DoD

OUT 52219

P 051536Z

1963 NOV 5 16 16Z

FM CIA WASHDC

TO RUCSBR/SAC OFFUTT AFB, OMAHA, NEB

RUCVAB/4080 STRAT WG, OL 19, BARKSDALE AFB, LA

RUEAHQ/DIAXX

RUECYG/NAVY PIC

5 NOV 1963

RUWBKG/15TH AF, MARCH AFB, RIVERSIDE, CALIF

RUWGAA/2D RTS, BARKSDALE AFB, LA

RUWGAA/2AF, BARKSDALE AFB, LA

DA GRNC

BT

SECRET

CITE CIA-Z-994

15TH AF (FOR DI); SAC (FOR DIM, BRASS KNOB, DOCR, DM 4) 2D AF
(FOR DI). FROM NATIONAL PHOTOGRAPHIC INTERPRETATION CENTER.

1. CAMERA B 7 WAS USED IN MISSION 3763 FLOWN ON 31 OCTOBER
1963; PROCESSING WAS ACCOMPLISHED BY NAVY PIC.

2. ORIGINAL NEGATIVE:

A. THE EXPOSURE IS ADEQUATE AND THE RESOLUTION IS GOOD.

B. 9R SIDE: THERE IS A SLIGHT INBOARD EDGE FOG ALONG THE
FIRST 50 FRAMES. A MANUFACTURER'S SPLICE APPEARS IN FRAME 41
AND HEAT SPLICES ARE PRESENT IN FRAMES 267, 1359, 1405, AND 1499.
PINHOLES AND BLISTERS ARE NOTED IN FRAMES 273, 438 AND 2307.
THERE ARE CRIMPS AND HANDLING MARKS IN FRAME 1359 AND 1597. A
PIECE OF FOREIGN MATTER IS ADHERED TO THE EMULSION IN FRAME 1463
AND THERE ARE MINOR SCRATCHES IN FRAME 1499.

C. 9L SIDE: THERE IS A SERIES OF MINUS DENSITY DOTS 2.0"

HFS

CJS

CFC

PNS

ACL

Grace (File)

1

GROUP 1
Excluded from automatic
downgrading and
declassification

FROM THE OUTBOARD EDGE SPACED 1.55" APART THROUGHOUT THE MISSION. DIRT IS NOTED IN FRAME 1863 AND BLISTERS ARE PRESENT IN FRAMES 838, 1518, AND 2053. THERE IS A CHEMICAL MARK IN FRAME 1928.

D. BOTH SIDES: THERE WERE NO CAMERA MALFUNCTIONS DURING THIS MISSION. FRAMES 1 THROUGH 942 ON THE 9L SIDE CONTAIN BASE SCRATCHES AND FRAMES 1359 THROUGH 2364 ON THE 9R SIDE CONTAIN SIMILAR SCRATCHES WHICH HAVE BEEN DETERMINED TO HAVE OCCURRED AT THE PROCESSING SITE. THERE WERE 2364 EXPOSURES IN THIS MISSION.

3. POSTIVE:

A. THE PI SUITABILITY IS GOOD. THE PRINTING AND PROCESSING OF THE POSITIVES ARE GOOD.

B. CLOUDS COVERED 20 PERCENT OF THE MISSION.

S E C R E T

END OF MESSAGE

(ABOVE MSG WAS ALSO PASSED TO CIA WATCH (CGS))